

F-7-2

Inventory Number:
Rock Hall
Frederick Co, MD
C. Mazurek
February 1999
Section 8.1

Addendum

Rock Hall is located at 101-C Dr. Belt Road, off of Furnace Branch Road, in Frederick Co, within the Monocacy Natural Resources Management Area.

This property is part of the Resident-Curatorship Program within the Maryland Department of Natural Resources, with the curators Jon and Sally Mullen undertaking the restoration. The house is very well maintained, on both the interior and exterior.

The log outbuilding adjacent to the main house has been moved to a different location, with all that remains on site the stone chimney. In addition a garage has been built to the east of the house and landscaping, such as perennial beds, have been installed around the property. The superstructure of the bank barn to the south of the main house has been lost, except for the remains of the fieldstone foundation and a portion of the stone silo. A modern barn that appears to date from the mid part of the twentieth century stands close by, and appears to still be in use for the storage of hay. The remains of an iron furnace, with remnants of slag, lay to the east about ½ a mile through the woods.

Inventory Number: F-7-2
Rock Hall Tenant House
Frederick Co., MD
C. Mazurek
February 1999
Section 8.1

Addendum

The Rock Hall Tenant House located within the Monocacy Natural Resources Management Area is no longer standing.

MARYLAND HISTORICAL TRUST

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

Rock Hall

AND/OR COMMON

2 LOCATION

STREET & NUMBER

South Side Furnace Branch Road

6th F.D. 7

CITY, TOWN

CONGRESSIONAL DISTRICT

Maryland

VICINITY OF Dickerson

Frederick

STATE

COUNTY

3 CLASSIFICATION

CATEGORY

☐ DISTRICT☒ BUILDING(S)☐ STRUCTURE☐ SITE☐ OBJECT

OWNERSHIP

☒ PUBLIC☐ PRIVATE☐ BOTH

PUBLIC ACQUISITION

☐ IN PROCESS☐ BEING CONSIDERED

STATUS

☒ OCCUPIED☐ UNOCCUPIED☐ WORK IN PROGRESS

ACCESSIBLE

☐ YES: RESTRICTED☐ YES: UNRESTRICTED☒ NO

PRESENT USE

☐ AGRICULTURE☐ MUSEUM☐ COMMERCIAL☐ PARK☐ EDUCATIONAL☒ PRIVATE RESIDENCE☐ ENTERTAINMENT☐ RELIGIOUS☐ GOVERNMENT☐ SCIENTIFIC☐ INDUSTRIAL☐ TRANSPORTATION☐ MILITARY☐ OTHER**4 OWNER OF PROPERTY**

NAME

State of Maryland Dept. of Natural Resources Telephone #:

STREET & NUMBER

Tawes Office Building

Maryland 21401

CITY, TOWN

STATE, zip code

Annapolis

VICINITY OF

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE

REGISTRY OF DEEDS, ETC.

Frederick County Courthouse

Liber #:

Folio #:

STREET & NUMBER

N. Court Street

Maryland 21701

CITY, TOWN

STATE

Frederick

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

Inventory of Historical Sites in Western Montgomery and Frederick Counties

DATE

Spring, 1975

☐ FEDERAL ☐ STATE ☐ COUNTY ☒ LOCALDEPOSITORY FOR
SURVEY RECORDS

Sugarloaf Regional Trails

CITY, TOWN

Dickerson

STATE

Maryland

7 DESCRIPTION

F-7-2

CONDITION

☒ EXCELLENT
☐ GOOD
☐ FAIR

☐ DETERIORATED
☐ RUINS
☐ UNEXPOSED

CHECK ONE

☐ UNALTERED
☒ ALTERED

CHECK ONE

☒ ORIGINAL SITE
☐ MOVED DATE _____

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

"The large, two-story, two-part main house was constructed of local stone in 1812 by Roger Johnson, a brother of Thomas Johnson, Maryland's first elected State governor. Of typical Federal styling, the principal facade is three bays wide and has a transomed entrance door occupying an end bay. The A-frame roof has a single brick chimney at each end of the ridge line; a centered cross gable added on the front roof slope in the mid-nineteenth century was removed several years ago but traces of its outline can still be discerned. On the west elevation the fenestration of the facade is repeated, but without a doorway. Visible alterations in the stonework below the middle first floor window suggests that a door might have previously occupied this location. All of the windows of the main block apparently had exterior blinds but they were probably paneled and not the existing louvered ones. On the interior the first floor room configuration consists of three rooms (see plan), an alteration of its original four room plan. The woodwork of the front drawing room is the best in the house and incorporates simplified classical motifs popular during the Federal period. It is obvious, however, that some replacement of the woodwork has occurred and, in fact, some of it may constitute later introductions. The stair is apparently original and rises in two flights to three second floor bed chambers. In the attic, accessible from the attic of the north wing, can be seen one of the more interesting architectural features of the house. Heavily framed, it recalls earlier methods of construction, employing massive principal rafters, collars, purlins, and wind braces.

On the north end of the principal block stands a later, two-story, stuccoed stone wing which, it is believed, incorporated into its plan an earlier detached or semi-detached kitchen. The facade of the wing is covered by a two-story galleried porch. The cornice decoration of the main block, consisting of ogee and turned moldings and applied fretwork on the bed molding, is continued over onto the cornice of the wing. Although the cornice is of Federal character and probably original to the main block its use on the wing provided a continuity of design. That the wing is later is confirmed by structural documentation. The wing contains two first floor rooms. The north room, with a large fireplace opening, constitutes the original kitchen. Upstairs are two bedchambers. Although there is a two-room, full cellar beneath the main block there is only a partial cellar beneath the wing.

Within several feet of the north end of the wing stands a small log cabin that appears to have been built about 1825-40. Although its walls and roof appear to be contemporary to one another the first floor ceiling joists were obviously removed from an earlier structure. A second log building stands several yards back from the rear wall of the wing. It has been extensively remodeled and is in an advanced state of deterioration. Its original purpose and date of construction are unknown. (The possibility exists that both cabins were moved here from other locations on or near the property.)

CONTINUE ON SEPARATE SHEET IF NECESSARY

.RIOD		AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW		
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES

1812

BUILDER/ARCHITECT

Roger Johnson

STATEMENT OF SIGNIFICANCE

"The historical significance of the Rock Hall property is readily apparent. Not only does the property have a history of industrial use, but also a close tie with the Johnson family, who played such a major role in the socio-economic development of the region. The house itself is deserving of recognition as one of the few buildings in the area which so adequately represents the ideas and ideals of the New Republic as manifested in its architecture. Its simple character is consistent with the nature of the region at that time and is typical of almost all of the Johnson houses erected by that family in Frederick County."¹ Local residents have expressed a desire to have the property considered for National Register listing and I can foresee no difficulties in this regard, provided there is sufficient documentation for the furnace complex and the development of the house and property throughout the nineteenth and early twentieth century (including alterations made to the house by the previous owners).

¹Memorandum of J. Richard Rivoire to Arthur C. Townsend

CONTINUE ON SEPARATE SHEET IF NECESSARY

F-7-2

9 MAJOR BIBLIOGRAPHICAL REFERENCES

Grove, William J. History of Carrollton Manor 1929
Dwyer, Michael F. A Brief History of Rock Hall Part 1 of a two part series.
Rivoire, R. Richard Memorandum to Arthur C. Townsend Maryland Historical Trust, on Rock Hall. 10-30-74

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY _____

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE	Maryland	COUNTY	Montgomery
STATE		COUNTY	

11 FORM PREPARED BY

NAME / TITLE Cherilyn Widell, Sites Analyst

Frederick City Office of Historic Preservation	3/6/78
ORGANIZATION	DATE

Winchester Hall, 12 E. Church St.	663-8300 ext. 266
STREET & NUMBER	TELEPHONE

Frederick	Maryland
CITY OR TOWN	STATE

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438

F-7-2

Description of Rock Hall (continued)

Also on the property, and within several hundred feet of the house, is a large frame bankbarn. Although employing an earlier type of framing system it was undoubtedly built during the last decade of the nineteenth century (or even later). It does, however, join an interesting stone silo that appears to remain from an earlier structure."¹

¹Memorandum of J. Richard Rivoire to Arthur C. Townsend 10/30/74

ADDENDA

In 1984 the Department of Natural Resources contracted with Joe Getty to conduct a follow-up survey of selected historic properties on DNR lands. DNR funded the field survey and photography but did not prepare finished copy. The attached photocopy pages were forwarded to the Maryland Historical Trust to supplement existing files. All original material and photographs remain in the possession of the Department of Natural Resources under the supervision of Ross Kimmel (x3771).

**Maryland Historical Trust
State Historic Sites Inventory Form**

Survey No. F-7-2

Magi No.

DOB ☐ yes ☐ no

1. Name (indicate preferred name)

historic

and/or common

Rock Hall Tenant House

2. Location

street & number north side of Dickerson Road at Frederick/Montgomery County line ☐ not for publication

city, town

Dickerson

☒ vicinity of

congressional district

Sixth

state

Maryland

county

Frederick

3. Classification

Category

☐ district

☒ building(s)

☐ structure

☐ site

☐ object

Ownership

☒ public

☐ private

☐ both

Public Acquisition

☐ in process

☐ being considered

☐ not applicable

Status

☐ occupied

☒ unoccupied

☐ work in progress

Accessible

☒ yes: restricted

☐ yes: unrestricted

☐ no

Present Use

☐ agriculture

☐ commercial

☐ educational

☐ entertainment

☐ government

☐ industrial

☐ military

☐ museum

☐ park

☐ private residence

☐ religious

☐ scientific

☐ transportation

☒ other: none

4. Owner of Property (give names and mailing addresses of all owners)

name

Department of Natural Resources

street & number

Towers State Office Bldg.

telephone no.: 289-3771

city, town

Annapolis

state and zip code MD 21401

5. Location of Legal Description

courthouse, registry of deeds, etc.

Frederick County Courthouse

liber

street & number

South Court Street

folio

city, town

Frederick

state MD

6. Representation in Existing Historical Surveys

title

Frederick County Survey

date

3/6/78

☐ federal ☒ state ☒ county ☐ local

depository for survey records

Maryland Historical Trust

city, town

Annapolis

state MD

7. Description

Condition

☐ excellent
☐ good
☐ fair

☒ deteriorated
☐ ruins
☐ unexposed

Check one

☐ unaltered
☒ altered

Check one

☒ original site
☐ moved date of move _____

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The Rock ~~NEW~~ ^{Hall} Tenant House is a two-story, three-bay by one-bay frame structure with a log ell, ~~wing~~. Most of the materials in the structure date from mid-to-late nineteenth century. From interior construction, it is evident that the log structure was built first, perhaps in the mid-nineteenth century, and that the frame main section was added in the 1860s-80s. The main section of the three-bay main facade has a central entrance. Wood trim and interior moldings also date from the nineteenth century.

The structure is an ell-shaped structure and contains no fireplaces, only stove flues. There are flue chimneys at each gable end of the main section and at the gable end of the ell. The main section is constructed of two-by-four framing with four-by-four posts. Floor joists are two-by-eights. The structure is laid on a field ^Cstone foundation. The original exterior sheathing was ~~an~~ eight-inch ^{wide} wood siding. This has been covered with a mid-twentieth century abestos siding. The central entrance has a five-panel door with a central horizontal panel and a two-pane transom. Windows in the outer bays of the first story ^{and} ~~of~~ the three bays of the second story are six-over-six sash windows. The structure has a box corner ^{ice} ~~or~~ and the roof is covered with ~~a~~ corrugated sheet metal. The north gable end of the main section has a single six-over-six window on each story and a small four-pane window in the gable. ¶ The site slopes slightly to the south so that the south gable end of the main section has a basement entrance at ground level. It has six-over-six window on the first and second story above the foundation entrance and a four-pane

window in the gable. The box cornice returns at the corners, ~~and~~. Also on this gable end is a porch that extends half way to the gable and back through the total length of the ^{ell.} ~~wing~~. There is an exterior door onto the porch from the main section that contains a five-paneled ~~doorway~~. The original exterior sheathing was applied with fully-mature wire nails. The structure had corner boards and plain board frames around the doors and windows.

The rear wing stood originally as a ^{sixteen-by-eighteen foot} ~~wood~~ log structure. It was built slightly into the slope with a stone foundation. The structure was built of eight-inch wide logs that were V-notched and then covered in a seven-inch ^{wide} ~~wood~~ siding. It does not appear that the east gable end of the structure ever contained a fireplace. There is a brick stove flue chimney at this end. There is also a corner stair ^{in the southwest corner of the room.} ~~entry cornered brick~~ ~~chimneys~~.

The main section interior consists of a central stairway with a small entrance foyer. A single room was located on each side of the stairway with a small ^{closet} ~~cupboard~~ underneath the stair. The woodwork on the interior ^{contains} ~~has~~ ^{ed} molding window ~~frame~~ and door frames typical of the late nineteenth century.

3. Significance

Survey No. F-7-2

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> humanitarian
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> theater
<input type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics government	<input type="checkbox"/> transportation
		<input type="checkbox"/> invention		<input type="checkbox"/> other (specify)

Specific dates

Builder/Architect

check: Applicable Criteria: ☐ A ☐ B ☐ C ☐ D
and/or

Applicable Exception: ☐ A ☐ B ☐ C ☐ D ☐ E ☐ F ☐ G

Level of Significance: ☐ national ☐ state ☐ local

Prepare both a summary paragraph of significance and a general statement of history and support.

Significance

The Rock Hall Tenant House shows a representative tenant structure for a central Maryland large farm. ^{While} ~~By~~ the main house at Rock Hall is substantial with refined ornamentation, the tenant structure is quite plain and modest in ornamentation and style. Originally, it was a sixteen by eighteen foot log house. It was constructed in a typical log house style from this area, built on a stone foundation into a slope with ground access to the foundation on the main facade. The logs were V-notched with wide spaces filled with chinking. The attic had a common rafter roof and the plate was elevated above the second-story floor joist by about three feet.

Also representative is the way this house was expanded during the 1860-80s. The original log structure became an ell for a larger tenant house. This house was constructed of a wood frame covered in wood siding. It had a two-room plan with a central stair partitioned between the two rooms.

The structure is in a deteriorated condition due to water damage from leaks in the roof.

42. "Rock Hall" - This home of Roger Johnson, on the Johnson furnace site, is said to have been built in 1812, with a later addition. It was built of red and white quartzite rock, also used to build the C&O Canal 7 arch aqueduct over the Monocacy, and was quarried on the property. The oldest section remains stone, and the addition has stucco over stone. Records show the stone mason was paid \$550 for building the shell of the house. Window glass, still intact is said to have been made of the property. Could it have been the Aetna Glassworks at the Johnson's Bush Creek Site? The home is now being restored by Mr. Jon Mullen, who holds a long-term lease. There are remains of a number of buildings on the property including a grist mill and lime kilns. (State of Maryland, Dept. of Natural Resources)



42. Rock Hall

Urbana Civic Association
1976 History and Legends of Urbana Election District.
Frederick High School Press, Frederick, MD.


43. "Labyrinth" - The date of the building of this home is not known, but it does show on the 1873 map. The main portion of the house is built of field stone and has walls two feet thick, and 12 by 12 beams. The stone was covered years ago with stucco, except for the north end, where the upper third is covered with patterned slate. The kitchen addition is of bricks which are said to have been brought from England as ballast. The upper front porch and decorative railings were a later addition. It is said there was a kitchen attached to the rear of the house which was later removed. The kitchen and living room fireplaces use the same chimney.

According to deeds the property has been designated as *Labrinth*, (*Labranth*, *Labarinth*), *McKays Chance*, *McKays Choice*, *None Left*, *Williams Chance*, *Red Oak Knoll*, *Wilson's Discovery*, *Stony Hive*, *Strife Ended*, *Right and Justice*, and *Plummers Delight*.


The house has been owned and tenanted for the most part by the descendants of Samuel Simmons, (died 1779) and Belinda Simmons. A small cemetery at the corner of Linthicum and Thurston Roads has a large stone for this family.

Previous owners included Levi Phillips and Eleanor, Caleb Knott, Josua and William Knight, William Knight and Sarah, and William McKay. Sarah Knight, widow of William, freed her female slave and two children by Writ of Manumission on April 10, 1797.

(Dyker)



43. Labyrinth




F-7-2

MONOCACY NATURAL RESOURCES AREA


ROCK HALL TENANT HOUSE

F-7-2

scale $\frac{1}{4}'' = 1 \text{ foot}$



F-7-2



U.S.G.S. MAP
POOLESVILLE, MD.

F-7-2

Poolesville Quad


F-7-2

UNITED STATES
DEPARTMENT OF THE ARMY
CORPS OF ENGINEERS

FREDERICK 13 MI
BUCKEYSTOWN 5.6 MI


(BUCKEYSTOWN)

(1243
Sgt. Davis)





F-7-2

- 2 Rock Hall Tenant House
- p- West & South Facades
- c- West & North Facades
- n- North Facade of Ell





2 Rock Hall Tenant House
 - East Facade of Ell
 pt - West Facade - Entrance
 right - Wall framing between 2 sections





F-7-2


-7-2 Rock Hall Tenant House
6 SECTION
Top - Northeast corner
Center - Southwest corner
Bottom - 2nd floor - southeast corner



F-7-2 ROCK HALL TENANT HOUSE
MAIN SECTION
top. Northeast corner
bottom. Roof framing

F-7-2







2 9'99

F-7-2

ROCK HALL

FREDERICK CO., MONOCACY NRMA

C. MAZUREK

2/9/99

DEPT. OF NATURAL RESOURCES
FRONT FAKAR (WEST)

1 OF 22

00-02 111111+0000 1203



66.6.2
9.9.9

F-7-2

Rock Hall

FREDERICK CO., MONKAKY NRMA

C. MAZUREK

2/9/99

DEPT. OF NATURAL RESOURCES

LEFT SIDE OF FRONT FACADE (WEST)

2 OF 22



2 9 '99

F-7-2

ROCK HALL

FREDERICK CO., MONOCACY NRMA

C. MAZUREK

2/9/99

DEPT. OF NATURAL RESOURCES

RIGHT SECTION OF FRONT FACADE (WEST)

4 OF 22



F-7-2

ROCK HALL

FREDERICK CO., MONOCACY NRMA

C. MAZUREK

2/9/99

DEPT. OF NATURAL RESOURCES

MIDDLE SECTION OF FRONT FACADE (WEST)

3 of 22



2 9'93

F-7-2

ROCK HALL

FREDERICK CO., MONOCACY NRMA

C. MAZUREK

2/9/99

DEPT. OF NATURAL RESOURCES

ROAR FACADE (EAST)

#5 OF 22

2021 12:00 PM 02-09 11:11 00-05 144444+00PM 1200



F-7-2

ROCK HALL

FREDERICK CO., MONOCACY NRMA

C. MAZUREK

2/9/99

DEPT. OF NATURAL RESOURCES

REAR FACADE (EAST), LEFT SIDE

6 OF 22



2 9'99

F-7-2

ROCK HALL

FREderick CO., MONOCACY NRMA

C. MAZUREK

2/9/99

Dept. of NATURAL RESOURCES

REAR FACADE (EAST), MIDDLE SECTION

7 OF 22



2 9'99

F-7-2

ROCK HALL

FREDERICK CO., MONOCACY NRMA

C. MAZUREK

2/9/99

DEPT. OF NATURAL RESOURCES

REAR FACADE (EAST), RIGHT SECTION

#8 OF 22



2 9'99

F-7-2

ROCK HALL

FREDERICK CO., MONOCACY NRMA

C. MAZUREK

2/9/99

DEPT. OF NATURAL RESOURCES

DETAIL OF FRONT FACADE WINDOW, (LEFT SIDE), WEST.

#9 of 22



2 9'99

F-7-2

ROCK HALL

FREDERICK CO., MONOCACY NRMA

C. MAZUREK

2/9/99

DEPT. OF NATURAL RESOURCES

DETAIL OF CORNICE, FRONT FACADE, WEST.

10 OF 22



2 9'99

F-7-2

ROCK HALL

FREDERICK CO., MONOCACY NEMA

C. MAZUREK

2/9/99

DEPT. OF NATURAL RESOURCES

LANDSCAPE, FACING NORTH

11 OF 22

16 00-04 111111+0000 1203



2 8'98

F-7-2

ROCK HALL

FREDERICK CO., MONOCACY NRMA

C. MAZUREK

2/9/99

DEPT. OF NATURAL RESOURCES

LANDSCAPE, FACING WEST

12 OF 22

2017 08-04 AM 11:11:00 PM 1203



2 9'99

F-7-2

ROCK HALL

FREDERICK CO., MONOCACY NRMA

C. MAZUREK

2/9/99

DEPT. OF NATURAL RESOURCES

SOUTH FACADE

13 OF 22

012 00-05 HHHHH+GGRN 1203



66,60 2

F-7-2

ROCK HALL

FREDERICK CO., MONOCACY NRMA

C. MAZUREK

2/9/99

DEPT. OF NATURAL RESOURCES

NORTH FACADE

14 of 22

2025 11:08:11 AM 20-08-01 11:08:11 AM 1203



F-7-2

ROCK HALL

FREDERICK CO., MONOCACY NRMA

C. MAZUREK

2/9/99

DEPT. OF NATURAL RESOURCES

GARAGE, NORTH FACADE

15 OF 22

025 00-03 NH+NH+GRN 1203



F-7-2

ROCK HALL (VICINITY)

FREDERICK CO., MONOCACY NRMA

C. MAZUREK

2/9/99

DEPT. OF NATURAL RESOURCES

STONE SILO

16 OF 22

100-01 1111111111111111 1200



2
5' 10"

F-7-2

ROCK HALL (VICINITY)

FREDERICK CO., MONOCACY NRMA

C. MAZUREK

2/9/99

DEPT. OF NATURAL RESOURCES

STONE SILO.

17 OF 22

006 08+00 14444+00R1 1200



F-7-2

ROCK HALL (VICINITY)

FREDERICK CO., MONKAKY NRMA

C. MAZUREK

2/9/99

DEPT. OF NATURAL RESOURCES

LOWER STRUCTURE OF STONE BANK BARN (INSIDE VIEW)

19 OF 22



2 9'99

F-7-2

Rock Hall (Vicinity)

FREDERICK CO., MANOKAY NRMA

C. MAZUREK

2/9/99

Dept. OF NATURAL RESOURCES

WOOD BARN

#20 of 22



2 9'09

F-7-2

ROCK HALL (VICINITY)

FREDERICK CO., MONOCACY NRMA

C. MAZUREK

2/9/99

DEPT. OF NATURAL RESOURCES

WOOD BARN

20 OF 22

00-02 N44W44G00N 1200



2-9-99

F-7-2

ROCK HALL (VICINITY)

FREDERICK CO., MONOCACY NRMA

C. MAZUREK

2/9/99

DEPT. OF NATURAL RESOURCES

CONCRETE BLOCK DAIRY BARN

21 OF 22

00-01 11444+0001 1208



2
9'95

F-7-2

ROCK HALL (VICINITY)

FREDERICK CO., MONOCACY NRMA

C. MAZUREK

2/9/99

DEPT. OF NATURAL RESOURCES

CONCRETE BLOCK DAIRY BARN

22 OF 22



F-7-2

MON/DNR 1

ROCK HALL

MONOCACY N.R.M.A.

7/78 JDH



F-7-2

MON/DNR 1

ROCK HALL

MONOCACY N.R.M.A.

7/78 JDH



F-7-2

MON/DNR 1

ROCK HALL

MONOCACY N.R.M.A.

7/78 JDH

DETAIL, CORNICE ~

FACADE
5



F-7-2

ROCK HALL

Minocacy N.R. MA.

Interior: detail, stairs (hallway,
principal block)

9/79

E K. COX



F-7-2

MON/DNR 14

LOG CABIN @ ROCK HALL

MONOCACY N.R.M.A.

7/78 JDH



F-7-2

MON/DNR 9

BARN @ CHADWICK PROP. (ROCK HALL)

MONOCACY N.R.M.A.

7/78 JDH



F-7-2

ROCK HALL

Monocacy Natural Resources Mgmt. Area

Interior: fireplace wall, parlor

9/79

E.K. Cox



F-7-2

ROCK HALL

Monocacy Natural Resources Mgmt. Area

Detail: parlor mantel

9/79

E.K. Cox



F-7-2

MON/DNR 4

TENANT HOUSE (CHADWICK) @ ROCK HALL
MONOCACY N.R.M.A.

7/78 JDH